

Test Report No. XMNMLC1800489803 Date: 13 Jun 2018 Page 1 of 3

FOSHAN IFORLONG PLASTIC MATERIAL MANUFACTURE CO.,LTD

NO. 21-2 (F3), AREA D, LUBAO PARK, SANSHUI CENTER TECHNOLOGY ZONE, FOSHAN CITY, GUANGDONG PROVINCE, CHINA

The following sample(s) was/were submitted and identified on behalf of the clients as: Iforlong PVC Flooring

SGS Job No.: XMIN180500775CCM - XM

Specification: 2.0mm*2.0m*20m

Client Ref. Info. : Thickness:2.0mm

Date of Sample Received: 03 May 2018

Testing Period: 03 May 2018 - 13 Jun 2018

Test Requested: Selected test(s) as requested by client.

Test Method: Please refer to next page(s).

Test Results: Please refer to next page(s).

Signed for and on behalf of SGS-CSTC Standards Technical Services Co., Ltd. Xiamen Branch

Sunny Lu

Approved Signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No. 31 Xianghong Road, Xiang' An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5766995 f (86-592) 5766999 中国・福建・厦门市火炬(翔安)产业区翔虹路31号

邮编: 361101 t (86-592) 5766995 f (86-592) 5766999

e sgs.china@sgs.com

www.sgsgroup.com.cn



Test Report

No. XMNMLC1800489803

Page 2 of 3

Date: 13 Jun 2018

Test Results:

Test Part Description:

Specimen No. SGS Sample ID Description

XMN18-004898.001 Multicolor(brown, gray, lt-gray) surfaced white plastic SN1

Remarks:

(1) 1 mg/kg = 0.0001%

(2) MDL = Method Detection Limit

(3) ND = Not Detected (< MDL)

(4) "-" = Not Regulated

Formaldehyde

Test Method: With reference to EN 717-1:2004, analysis was performed by UV-Vis.

<u>MDL</u> Test Item(s) <u>Unit</u> <u>001</u> Formaldehyde Emission (In air) 0.080 ND mg/m³

Notes:

(1) mg/m³ = milligrame per cubic meter

(2) Reference Limit: BS EN 13986:2004+A1:2015 Formaldehyde class E1: ≤0.124 mg/m³ air Formaldehyde class E2: >0.124 mg/m³ air

(3) The test was subcontracted to SGS Guangzhou chemical lab.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.


Attention: To check the authenticity of testing (inspection report & certificate, please contact us at telephone: (86-755) 8307 1443.



Test Report

No. XMNMLC1800489803 Date: 13 Jun 2018 Page 3 of 3

Sample photo:



SGS authenticate the photo on original report only

*** End of Report ***



No. 31 Xianghong Road, Xiang' An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5766995 f (86-592) 5766999 www.sgsgroup.com.cn

邮编: 361101 t (86-592) 5766995 f (86-592) 5766999

中国・福建・厦门市火炬(翔安)产业区翔虹路31号

e sgs.china@sgs.com